



THE EASTERN SPECIALTY COMPANY

SW Release Notes



Company : TESCO – The Eastern Specialty Company
Project : Tesco Device Manager (TDM)
SW Version : 1.1.1r
Release Date: November 7, 2022

Contents

TDM SW Revisions: 2

TDM SW Compatibility:..... 2

TDM SW Features Update: 2

TDM SW Bug Fix..... 2

NextGen Software Revisions:..... 3

NextGen Software Compatibility: 3

NextGen Software Features Update:..... 3

NextGen Software Bug Fix: 3

CAT. 6330 Software Revisions: 4

CAT. 6330 Software Compatibility: 4

CAT. 6330 Software Features Update:..... 4

CAT. 6330 Software Bug Fix: 4

CAT. T4000 Software Revisions:..... 5

CAT. T4000 Software Compatibility: 5

CAT. T4000 Software Features Update:..... 5

CAT. T4000 Software Bug Fix: 5



THE EASTERN SPECIALTY COMPANY

SW Release Notes

TDM SW Revisions:

Base Software: 1.1.0r

New Software: 1.1.1r

TDM SW Compatibility:

1. This application is compatible only for NextGen devices with a firmware version of 3.0.1r
2. This application is compatible only for CAT. 6330 devices with a firmware version of 1.3.1r
3. This application is compatible only for CAT. T4000 devices with a firmware version of 1.3.1r
4. Database version 4.1.0r

TDM SW Features Update:

1. Created a comparison popup for bulk testing screen when the meter setup information does not match the serial in the database
2. When creating a new sequence, the popup is populated with a default sequence
3. Added a contact us popup
4. Added an about menu

TDM SW Bug Fix

1. Can no longer launch several instances of TDM



THE EASTERN SPECIALTY COMPANY

SW Release Notes

NextGen Software Revisions:

Base Software: 3.0.0r

New Software: 3.0.1r

NextGen Software Compatibility:

- VRMs must be: VRM-MB, 5.3.0 or VRM-MB, 5.3.1 or VRM-MB, 5.3.2 or the VRM-MA / VRM-BL software
- FPGA must be version 1.3.2 or 1.3.4

NextGen Software Features Update:

1. Non-accuracy capable unit can run sequences with drive only tests

NextGen Software Bug Fix:

1. Cannot re-queue a sequence indefinitely anymore
2. Fixed test result screen. It would show a random phase when a channel is disabled
3. Fixed a bug where the app would crash then launch then crash forever when and older unit is updated



THE EASTERN SPECIALTY COMPANY

SW Release Notes

CAT. 6330 Software Revisions:

Base Software: 1.3.0r

New Software: 1.3.1r

CAT. 6330 Software Compatibility:

- MB-FPGA must be version "1.0.0S", "1.0.0r", "1.0.1r", "1.1.0r", "1.2.0r", "1.2.1r" or "1.2.2r"
- CT-FPGA must be version "1.0.0S", "1.0.0r", "1.0.1r" or "1.1.0r"

CAT. 6330 Software Features Update:

1. N/A

CAT. 6330 Software Bug Fix:

1. Cannot re-queue a sequence indefinitely anymore



THE EASTERN SPECIALTY COMPANY

SW Release Notes

CAT. T4000 Software Revisions:

Base Software: 1.3.0r

New Software: 1.3.1r

CAT. T4000 Software Compatibility:

- GFCI-MA: 1.1.6r
- PL4000-MA: 1.1.1r
- MB-FPGA must be "1.2.0r" or "1.2.1r"

CAT. T4000 Software Features Update:

1. N/A

CAT. T4000 Software Bug Fix:

1. Cannot re-queue a sequence indefinitely anymore